
CASE STUDY

PROCESS IMPROVEMENT IN DRY CAST MOLDING

BY: JIM LEONARD, SENIOR CONSULTANT
QUALITY SUPPORT GROUP

Quality
Support
Group



PROCESS IMPROVEMENT IN DRY CAST MOLDING

BY: JIM LEONARD, SENIOR CONSULTANT

[Note: Because of the sensitive nature of regulated medical materials and devices, the name of the client and product and process design details are not disclosed in this case study.]

In late 2000, a valued QSG client emerged from years of biomedical research in their laboratories outside London. One of their new products was a coating material that mimicked the hydration of the human cell. Applications of the new technology included coating stents used in angioplasty and coating contact lenses. Tests indicated that the stents coated with the new material were not rejected by the body anywhere near as often as others. Contact lens users reported that they could wear the company's coated lenses a lot longer than competitors' lenses without drying out, fatigue, or discomfort.

In the wake of its successful clinical trials, our client decided that it was time to "go commercial" with their new material; to start to produce and sell stents and lenses treated with their new coating. Senior management further decided that their strategy for commercialization would be to implement a Six Sigma initiative; that Six Sigma would be the methodology they would use to scale up and produce the new technology. I had the honor of teaching QSG's workshops on the statistical methods and providing consulting assistance to the senior management team and initial project teams in their operations in England, Ireland, and Virginia.

One of the first project teams was assigned to identify the major causes of rejected lenses after dry cast molding and then to introduce changes to the process to reduce the rate of rejects. Table A on page 2 lists the number and percentage of lenses rejected for all reasons in lens dry inspection after the molding process. The data were drawn from 20 lots produced over a three- month period. Inspectors rejected any lenses that exhibited one or more of the following defects:

- Miscount, No Lens, Water Spot
- Torn, Surface Chips, Split Edge
- Rust, Scratch, Rough Edges
- Holes, Flow Lines, Chipped Edge
- Bubbles


Figure 1 shows the run chart of the percent lenses rejected for any of the above reasons over the twenty selected lots. Because the lenses were produced in different-sized lots, it was appropriate to plot the percent lenses rejected (p) as opposed to the number of lenses rejected per lot. During the period represented by the data, the team had made several changes to the process. Causes of the defects were identified and corrective action was taken to eliminate or reduce the effects of the causes. Looking at their run chart, the team was pleased that their efforts had resulted in a downward trend in the percent lenses rejected throughout the summer.

2

Table A. Percent Lenses Rejected (p) After Dry Cast Molding

Lot/ Subgroup	No. of Dry Starts (n)	Number Rejected	Percent Rejected (p)
1	3759	458	.122
2	3108	343	.110
3	2140	333	.156
4	3710	418	.113
5	2580	268	.104
6	2378	211	.089
7	2106	203	.096
8	3095	409	.132
9	3465	311	.090
10	2876	247	.086
11	2685	320	.119
12	2555	282	.110
13	2510	252	.100
14	2510	260	.104
15	2676	314	.117
16	2941	346	.118
17	3834	313	.082
18	4068	267	.066
19	4766	359	.075
20	3780	228	.060
Totals:	61,542	6,142	

Figure 1. Percent Lenses Rejected (p) After Dry Cast Molding – All Reasons



The question, however, was not whether the rejects plotted in a downward trend. The question was whether there was a significant trend. The absence of a significant trend would indicate that the changes to the process did not really improve its outputs. On the other hand, a significant trend would reveal that the process changes indeed improved the process. The team proceeded to conduct a median test for non-random, special cause variation that is taught in QSG's Statistical Process Control (SPC) workshop. The trends test is summarized in Table B below.


Table B. Median Test for Non-Random, Special Cause Variation¹

1. Drawing a vertical line at the median of the points plotted will divide your chart into four quadrants, defined by the intersection of the median line and the central line (CL).
2. Beginning in the upper right-hand quadrant, label the quadrants I through IV in the clockwise direction.
3. Without counting any points on the median line or central line, total the number of points in the diagonal quadrants (I and III or II and IV) with the fewest number of points.
4. Conclude there is a significant (non-random) trend if the total is equal to or less than the "critical value" below.

Number of Points on Control Chart	Critical Value
7 or less	no test
8 – 11	0
12 – 14	1
15 – 17	2
18 – 20	3
21 – 23	4
24 – 25	5
26 – 28	6
29 – 31	7
32 – 33	8
34 – 36	9
37 – 38	10
39 – 41	11
42 – 43	12
44 – 46	13
47 – 48	14
49 – 51	15
52 – 53	16
54 – 56	17
57 – 58	18
59 – 60	19

After the project team applied the trends test to their run chart, they ended up with the graph shown in Figure 2 below. Diagonal quadrants I and III had the fewest number of points on the graph, so the total of 8 was used as the test value. When they compared the test value to the Critical Value for 20 points shown on Table B, the team discovered that the downward trend was not even close to being a significant trend (the test value of 8 was not equal to or less than the “critical value” of 3). Despite their best efforts, the trends test did not indicate that they had significantly reduced the level of rejects; i.e., had not improved the dry cast molding process.

Figure 2. Median Test Applied to Run Chart of Percent Lenses Rejected (p)



Needless to say, the project team members were extremely disappointed that all of their work – and the apparent downward trend in rejects – did not result in a significant trend. They were ready to give up! I urged them not to give up yet and suggested that they plot their data on a p Chart (for percent or proportion defective). What if, versus the p Chart control limits, their most recent lots' percent reject level was not low, but was significantly low? Might the p Chart deliver the good news they had hoped to get from the trends test?

The p chart is particularly useful in a setting like the dry cast molding process for two reasons. First, because of the complexity of the process and schedule demands, the team couldn't “stack the deck” to process an equal number of contact lenses in every lot or batch. Different lots had very different numbers of lenses. The p chart, however, allows one to take the data as they come, with no need to manipulate the measurements into standard samples or subgroups of equal size.

Second, the p chart automatically factors in how the same number of incidents will naturally have a different impact as a percentage on samples of different sizes. For example, in a department of ten employees, if one worker is absent, we will have a percent absenteeism rate of ten percent. In a group of twenty employees, one absence produces a percent absenteeism rate of only five percent.

The same number of incidents has a very different percentage impact on small groups versus large groups. In education, this is one reason small schools live in fear when district report cards of standardized test scores are published by the central office. If you're a small school (or class) you don't need many kids to score below grade level to look *terrible* as a percentage!

By the same token, over the three-month period reflected in this case study, some lots had as few as 2,100 lenses while another had over 4,800 lenses. It would be neither fair nor logical to compare such different-sized groups on a strict percentage basis (even though too many managers and auditors do it all the time). The p chart automatically factors in the reality of higher impacts as percentages on smaller groups.

Table C on page 6 shows the calculations of the central line control limits for the stability study and Figure 3 below provides the resulting p Chart. You will see that the process was not stable during the period represented by the data. Some of the percent rejected rates were above the upper control limit (UCL) early in the summer and the most recent lots' reject rates plotted significantly low (below the lower control limit or LCL). The project team was pleased to see that their efforts were indeed successful; they had improved the process; they had accomplished a statistically significant reduction in the percentage of lenses rejected after dry cast molding.

Figure 3. p Chart of Percent Lenses Rejected (p) After Dry Cast Molding – All Reasons




Table C. Data, Calculations and Control Limits for Lens Dry Inspection p Chart

						$\bar{p} + \text{and } \frac{-3\sqrt{\bar{p}(1-\bar{p})}}{\sqrt{n}}$	
Subgroup	No. of Dry Starts (n)	Number Rejected	p	\sqrt{n}	$\frac{3\sqrt{\bar{p}(1-\bar{p})}}{\sqrt{n}}$	UCL	LCL
1	3759	458	.122	61.3	.015	.115	.085
2	3108	343	.110	55.7	.016	.116	.084
3	2140	333	.156	46.3	.019	.119	.081
4	3710	418	.113	60.9	.015	.115	.085
5	2580	268	.104	50.7	.018	.118	.082
6	2378	211	.089	48.8	.018	.118	.082
7	2106	203	.096	45.8	.020	.120	.080
8	3095	409	.132	55.6	.016	.116	.084
9	3465	311	.090	58.9	.016	.116	.084
10	2876	247	.086	53.6	.017	.117	.083
11	2685	320	.119	51.8	.017	.117	.083
12	2555	282	.110	50.5	.018	.118	.082
13	2510	252	.100	50.1	.018	.118	.082
14	2510	260	.104	50.1	.018	.118	.082
15	2676	314	.007	51.7	.018	.118	.082
16	2941	346	.118	54.2	.017	.117	.083
17	3834	313	.082	61.9	.015	.115	.085
18	4068	267	.066	63.8	.014	.114	.086
19	4766	359	.075	69.0	.013	.113	.087
20	3780	228	.060	61.5	.015	.115	.085
Totals	61,542	6,142					

 p Chart Formulae:

$$CL = \bar{p} = \frac{\text{Total No. of Defectives}}{\text{Total No. of Samples}} = \frac{6,142}{61,542} = .100$$

$$\left. \begin{array}{l} \text{UCL} \\ \text{LCL} \end{array} \right\} = \bar{p} + \text{and } \frac{-3\sqrt{\bar{p}(1-\bar{p})}}{\sqrt{n}}, \text{ where } n = \text{subgroup size}$$


For too many Six Sigma projects, teams would be directed to complete the "Control" phase of DMAIC (Define-Measure-Analyze-Improve-Control). That is, they would be encouraged to establish control at the improved level of performance. I base all of my work on the teachings of Dr. W. Edwards Deming; and Point 5 of Deming's 14 Points for Management reads, "Constantly and forever improve every process for planning, production and service." Therefore, I advised the team to forget the Control phase. I did not want them to establish control at the current (though improved) level of defectives. I urged them – as I urge all of our clients – to institutionalize improvement so the reduction in defectives would continue in the wake of their successful project.

KISS Principle

When the data were first collected on the lenses rejected in lens dry inspection, the Quality Director wanted to plot each defect on a separate control chart. Recall that there were 13 different defect types that would result in a lens being rejected. Further recall that different production lots had different numbers of lenses. So, to fulfill the Quality Director's request the team would have had to set up and maintain thirteen separate u Charts (for rate of defects) – one for each type of defect.

I counseled the Quality Director against this plan. No matter what defect was discovered in lens dry inspection, the lens was rejected; the defect resulted in a defective. Therefore, I recommended that the team throw all rejected lenses into one bucket and continue to plot the data on the p Chart. The project team then backed up their control chart with the color-coded stacked bar chart shown in Figure 4 below. (A Pareto diagram could also have been used.)

Figure 4. Stacked Bar Chart of Reasons for Rejects in Lens Dry Inspection



When employing statistical process control, QSG encourages clients to always follow the “KISS” principle – keep it statistically simple! In this case, don’t try to maintain thirteen separate u charts when one p chart will do the job. If a defect or failure mode results in a total reject, plot the rejects on a p Chart or, for constant subgroup sizes, the np Chart. Then, back up the control chart with a Pareto diagram or, as used in this case, a stacked bar chart. The simple tool will let you know the priorities for short-term corrective action and the control chart will let you analyze the longer-term effects of your efforts to improve the process. (After all, Walter Shewhart invented the statistical process control chart as an analytic tool – not a control tool.)

Case Summary

As noted earlier, the data used for the control chart in this study were drawn from production lots molded and tested over a three-month period. The data summarized in Figure 4, however, cover the lens dry inspection results for the first twelve months of the plant’s operations. It’s impressive to see how the training, projects, and leadership drove yields up from 65% in the first month to 94% in month 12. Even more impressive is that this unquestioned progress was achieved during the same period of time that the plant went from two cast molding lines to nine cast molding lines; from 85 direct-labor employees to 320 direct-labor employees; from producing and shipping 200,000 compliant, packaged units per month to shipping more than 1.6 million compliant, packaged units per month.

It’s one thing to apply powerful statistical methods to accomplish improvements when working with a steady-state, mature process. It’s quite another thing to accomplish an improvement from 65% yields to 94% yields during the same period that you experience a four- to eight-fold expansion in production capacity, employment and shipping levels. Many of our client’s managers and employees played a part in the results documented in this case. We were pleased and honored to have had the opportunity to contribute to those results.

Notes

1K. Ishikawa, *Guide to Quality Control*, Asian Productivity Organization, Tokyo, Japan (1986), p. 217.

2J.F. Leonard, *The New Philosophy for K-12 Education: A Deming Framework for Transforming America’s Schools*, ASQ Quality Press, Milwaukee, WI (1996), pp. 136-137.